



TRAVAUX DE RÉFECION - FERMETURE DE LA PISTE 06D-24G

Du 15 août au 13 septembre*


Dans le but de maintenir ses installations aux normes de fiabilité et de sécurité, Aéroports de Montréal entreprend des travaux qui modifieront l'assignation habituelle des pistes.

Lorsque les vents sont du sud-ouest:

Décollages: Pistes 28 et 24D

Atterrissages: Piste 24D

Pas de décollages ni d'atterrissages sur la piste 24G.




Lorsque les vents sont du nord-est:

Décollages: Piste 06G

Atterrissages: Pistes 10 et 06G

Pas de décollages ni d'atterrissages sur la piste 06D.



Le choix des pistes est dicté par la direction des vents puisque les avions doivent décoller et atterrir face au vent.

* L'échéance des travaux peut varier en raison des conditions météorologiques

REPAIR WORK - CLOSURE OF RUNWAY 06R-24L

August 15 to September 13*


In an effort to maintain its facilities to reliability and safety standards, Aéroports de Montréal is undertaking repair work that will modify the runway assignment as follows:

When the winds are southwesterly:

Take offs: Runways 28 and 24R

Landings: Runway 24R

No take offs or landings on Runway 24L.




When the winds are northeasterly:

Take offs: Runway 06L

Landings: Runways 10 and 06L

No take offs or landings on Runway 06R.



Runway use is dictated by wind direction, since aircraft must take off and land into the wind.

* Could be extended depending on weather conditions